This MotoCAP safety rating applies to:

Brand	X-treme
Model	Red Wine
Type	Jacket - Leather
Date purchased	1 June 2023
Sizes tested	18 and 20
Test garment gender	Female
Style	All Purpose
RRP	$395.00

Test Results Summary	Rating	Score
MotoCAP Protection Rating	★★	48.7
Abrasion	9/10	6.80
Burst	10/10	1470
Impact	1/10	0.0
MotoCAP Breathability Rating	↙	0.104
Moisture Vapour Resistance	-	151.7
Thermal Resistance	-	0.263
Water resistance	N/A	N/A

Pockets are provided at the shoulders, elbows and back for fitting aftermarket impact protectors. Adding elbow and shoulder impact protectors would improve the protection levels of this garment. There are no vents to allow airflow movement through the garment.

Jacket and Pants - Crash Impact Risk Zones

This diagram is a pictorial representation of the crash impact risk Zones.

Removable liners

Thermal liner	☐
Water-resistant liner	☐

Removable impact protection

	Pockets	Armour
Elbow	✓	☐
Shoulder	✓	☐
Back	✓	☐

Zone 1	Zone 2	Zone 3	Zone 4
High risk of abrasion High risk of impact	High risk of abrasion	Medium risk of abrasion	Low risk of abrasion

Abrasion Resistance

The jacket was tested for abrasion resistance in accordance with MotoCAP test protocols. The diagram below is a visual indication of the likely abrasion performance of the materials in each zone calculated from the data in the table below. The colour coding is based on the worst performing material in each zone.

Abrasion Resistance Performance

Abrasion rating	9/10
Abrasion score	6.80

Determining Criteria	Area	Good	Acceptable	Marginal	Poor
High abrasion risk	Zones 1 & 2	> 5.6	3.0 - 5.6	1.3 - 2.9	< 1.3
Medium abrasion risk	Zone 3	> 2.5	1.8 - 2.5	0.8 - 1.7	< 0.8
Low abrasion risk	Zone 4	>1.5	1.0 - 1.5	0.4 - 0.9	< 0.4

Individual Abrasion Resistance Results: - The table below shows the test results for time to abrade through all layers of the materials. Calculated for each sample by Zone, type and area coverage of each material as a proportion of that Zone. Abrasion times are capped at a maximum of 10.00s.

Abrasion time for each test (seconds)

Zones 1 & 2	Coverage (%)	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5	Sample 6	Average	
Material A	50%	7.83	10.50	8.73	13.66	13.86	7.12	10.28	G
Material B	50%	3.93	4.82	5.00	3.94	3.64	6.88	4.70	A
Zone 3	Coverage (%)	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5	Sample 6	**Average**	
Material A	30%	7.83	10.50	8.73	13.66	13.86	7.12	10.28	G
Material B	70%	3.93	4.82	5.00	3.94	3.64	6.88	4.70	G
Zone 4	Coverage (%)	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5	Sample 6	**Average**	
Material B	100%	3.93	4.82	5.00	3.94	3.64	6.88	4.70	G

Details of materials used in jacket

Material A	Leather patch over leather shell, foam layer and fabric inner liner
Material B	Leather patch over leather shell with fabric inner liner

X-treme Red Wine
Leather Jacket

motocap.com.au

Burst Strength

The jacket was tested for burst strength in accordance with MotoCAP test protocols. The diagram below illustrates the burst strength results in terms of the likely performance of the garment in an impact and is a pictorial representation of the data from the table below.

Burst Strength Performance

Burst rating	10/10
Burst score	1470

Determining Criteria	Unit	Good	Acceptable	Marginal	Poor
Burst strength	(kPa)	> 1000	800 - 1000	500 - 799	< 500

Individual Burst Strength Results: - The table below shows the burst pressure in kilopascals (kPA) for each sample tested by Zone and the average result for each zone.

Burst pressure for each seam (kPA)

Area	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5	Sample 6	Average	
Zones 1 & 2	1565	1204	1691	1043	1994	1614	1519	G
Zones 3 & 4	1618	1579	1002	987	942	1534	1277	G

X-treme Red Wine Leather Jacket

Impact Protection

This jacket was not tested for impact protection as impact protectors were not provided with the garment. The diagram below is a visual indication of the likely performance of each impact protector calculated from the data in the table below. The colour coding is based on the worst performing score for average or maximum force for each impact zone. Areas shaded black are not considered for impact protection ratings.

Impact Protection Performance

Impact rating	1/10
Impact score	0.0

Determining Criteria	Unit	Good	Acceptable	Marginal	Poor*
Impact force	(kN)	< 15	15 - 24	25 - 30	> 30

* Poor may also indicate that no impact protector, or impact protector pocket is present in the garment

Impact Protector Results: - The table below shows the average and maximum force transmitted through each impact protector type in kilonewtons (kN) and their area of coverage as a proportion (%) of the Zone.

Impact protector type	Elbow	Shoulder
Average force (kN)	P	P
Maximum force (kN)	P	P
Coverage of Zone 1 area	0%	0%
Coverage of Zone after displacement	0%	0%

Individual Impact Protector Results: - The table below shows the test results for each strike on individual impact protectors in kilonewtons (kN) and the position of the strike. Individual strike results are capped at a maximum of 50kN.

Force transfer for each impact strike (kN)

Impact protector type	Elbow	No impact protector present		Shoulder	No impact protector present	
Strike location	Centre	Mid	Edge	Centre	Mid	Edge
Impact Protector 1						
Impact Protector 2						
Impact Protector 3						

**X-treme Red Wine
Leather Jacket**

Breathability

The jacket was tested for breathability following the MotoCAP test protocols. The table below shows the moisture vapour resistance and the thermal resistance values obtained.

Without removable liners		With water-resistant liner	
Breathability rating	↗	Breathability rating	N/A
Breathability score	0.104	Breathability score	N/A

Moisture Vapour Resistance - R_{et} (kPa.m^2/W)	1	2	Average
Without removable liners	152.8	150.5	151.7
With water-resistant liner	N/A	N/A	N/A

Thermal Resistance - R_{ct} (K.m^2/W)	1	2	Average
Without removable liners	0.260	0.266	0.263
With water-resistant liner	N/A	N/A	N/A

Water spray and rain resistance

This jacket has not been advertised as water-resistant so has not been tested for water spray and rain resistance.

Assessment Details.

Brand	X-treme
Model	Red Wine
Type	Jacket - Leather
Date purchased	1 June 2023
Tested by	AMCAF, Deakin University
Report approved by	MotoCAP Chief Scientist
Garment test reference	J23L16
Rating first published	July 2023
Rating updated	25 July 2023